


# Town of Westford, Massachusetts

## Asset Management Program

### Sidewalks- Distress Points Affecting PROWAG Compliance



### Condition Scoring

- "Good"**
- No surface distresses identified up to minor blemishes and deterioration observed on sidewalk.
  - Less than 10% of segment may need replacement.
- "Fair"**
- Surface distresses developing, but provide minimal to no impedance
  - 10% - 50% of segment may need replacement.
- "Poor"**
- Surface distresses and obstructions occur frequently, proving the sidewalk surface to be non-uniform and potentially unstable. (cracks, grass, depressions, bumps, patches, tree roots).
  - 50% - 100% of segment may need replacement.

### LEGEND

**Sidewalk Distress Points**


- Structural (1693)
- Maintenance (104)
- Vertical Obstruction (298)

**Sidewalk Condition (62.36 mi.)**

- Good (19.04 mi.)
- Fair (32.40 mi.)
- Poor (10.92 mi.)

**Roadways**

- Accepted
- State
- Unaccepted



Source: Esri, TomTom, Garmin, FAO, NOAA, USGS, © OpenStreetMap contributors, and the GIS User Community. Sources: Esri, Mapbox, Airbus DS, USGS, NOAA, NGA, CC-BY, N Robinson.