

---

## Survey Continued

### Interior Views of the Basement Vault



These metal containers are rusting from the dampness, and the papers inside are damp from the humidity in the room.



Portions of the ceiling are falling; the binders have hinges that are rusting due to the excessive dampness.

[Previous](#) | [Next](#)